

030150-HB-MD300-V01_EN

X

MD300 REPEATER PANEL - Art. 030150 -

QUICK GUIDE




Changes can be made without prior notice






Limotec bv Bosstraat 21, B-8570 Vichte www.limotec.be QUICK GUIDE



Changes can be made without prior notice





Key switch "Evacuation"

TIME DELAYS

Evacuation response time (1-9 minutes)	This is the time between the alarm notification on the fire alarm control panel and the acceptance of the alarm by means of the "Silence" button on the operating front of the MD300 control panel. If the alarm is not accepted after the response time has elapsed, the evacuation procedure will start.
Evacuation intervention time (1-9 minutes)	This is the time from accepting the alarm notification by means of the "Silence" button on the operating front of the MD300 control panel. If the alarm is not accepted after the intervention time has elapsed, the evacuation procedure will start. Restart the intervention time by pressing the "Silence" button on the operating front of the MD300 control panel.
Battery fault:	"Silence" does not affect the time delay.
10 minutes delayed	"Reset" restarts the time delay.
Mains voltage fault:	Is immediately reported in the control panel's log.
30 minutes delayed	"Silence" does not affect the time delay.
	"Reset" restarts the time delay.

(*) : contact your installer for the correct setting of the time delays.

Changes can be made without prior notice